

PD TEESPORT LIMITED

# NOTICE TO MARINERS NO.21 OF 2025

Issued by the Harbour Master on 06 January


NORTH-EAST COAST OF ENGLAND

RIVER TEES

## SLOW SPEED PASSING OF SVITZER WHARF

PD Teesport hereby gives notice that the requirement for slow speed passing of Svitzer Wharf remains in place, due to the mooring pontoon being damaged by vessels' wash.

Mariners are also reminded of the requirements of The Tees and Hartlepool Harbour Byelaws 1977 & 1985 Part II, Paragraph 6, <https://www.pdports.co.uk/wp-content/uploads/2019/04/PD-Teesport-Harbour-Byelaws-1977-1985.pdf>



Further information is available from TEES VTS on VHF Channel 14 or telephone 01642 277205.

**NOTE:** Owners, Agents and Charterers should ensure that the contents of this Notice are made known to Masters or persons in charge of their vessels or craft.

**Radar, AIS, CCTV, Telephone and VHF Channels are recorded 24/7.**

Harbour Master's Office, Ferry Road, Middlesbrough, TS2 1PL  
Administration: (01642) 277201 Email: [harbourmaster@pdports.co.uk](mailto:harbourmaster@pdports.co.uk)  
Tees VTS (24 hours): (01642) 277205 Email: [tees.vts@pdports.co.uk](mailto:tees.vts@pdports.co.uk)  
[www.pdports.co.uk](http://www.pdports.co.uk)